

Oil Field Environmental Incident Summary

Incident: 20141107173347 **Date/Time of Notice:** 11/07/2014 17:33
Responsible Party: Consolidated Well Services
Well Operator: ANSCHUTZ OIL COMPANY, LLC
Well Name: JACOBSON 1-29-134-104
Field Name: WILDCAT **Well File #:** 28350
Date Incident: 11/7/2014 **Time Incident:** 05:00 **Facility ID Number:**
County: SLOPE **Twp:** 134 **Rng:** 104 **Sec:** 29 **Qtr:** NW SW
Location Description: oil well site

Submitted By: Brant Gimmeson **Received By:**
Contact Person: unavailable atthistime
17TH STREET, SUITE 2400
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident: Other

	Spilled	Units	Recovered	Units	Reported to NRC:	Followup	Units
Oil					No		
Brine							
Other	100	Gallons	50	Gallons			

Description of Other Released Contaminant:

diesel from pump truck fuel tank

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

All on location, no ignition source, no danger to personell

Areal Extent:

5' x 25'

Potential Environmental Impacts:

contaminated soil, which will be removed

Action Taken or Planned:

inspect equipment and operations. back hoe dug a small hole fluid was vacced up. remaining contaminated soil will be placed on plastic on location with a berm. it will then be hauled to Fallon County landfill

Wastes Disposal Location: Fallon County Landfill Baker Montana

Agencies Involved: ND Dept of health
surface owners
ND O&G

Updates

Date: 11/10/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a fueling truck leak, remained on location according to the report. NDIC retains oversight.